

# 2015 BaoJun 610 After the replacement of airbags, the fault alarm lamp flashes to solve the operation method

Actual Measurement: BaoJun610, 2015, VIN=LZWADAGA2EB2\*\*\*\*\*, See as pic.

Fault phenomenon: After replaced new air bag and ECU, Instrument airbag warning light flashes regularly, see as pic:



operation Method:

- 1.Select Liu Zhou WuLin V20.32 above;
- 2.Select BaoJun 630;
- 3.Select SRS;



4. Select Mainland electronic SRS;



5. Select action test;



6. Select lock SDM;



7. Prompt “Communicating, Please wait…….”;



8. Follow the prompts to set to "ON". After the key is turned off, after the test run, the fault light is no longer flashing and the problem is solved.

END



长按指纹“识别二维码”关注 **golo官微**

投诉

