LAUNCH X-431 PAD III Engine Cover Not Closed Troubleshoot

Module:

2009 C200，VIN number：LE4GF4BBXAL10****;

Dash board shows cover is not closed can use this function to solve it.

Operating:

1). There are 3 error code shows when scan SAM mode.

Picture 1

2).Check the lock, switch, line normal or not. If normal then choose coding.

Picture 2

3). Choose "Parameter _ hood monitoring";

Picture 3

4). Item 001 current shows"Yes";;

图4

5).Choose item 001 change "Yes" into "No";



Picture 5

6).Choose "Write the code";

图6

7). Choose "Yes";

Picture 7

8). Close ignition switch then choose "Yes";

Picture 8

9). Turn on the ignition switch next then choose "Yes";

Picture 9

10). Wait for the mode to reset;

Picture 10

11).Code item 001 finished;

Picture 11

12).Now itme 001 shows "No" ;

Picture 12

13).SAM_DR mode become normal, fault resolution.

Picture 13