

Product Model	Date	Number
X431Pro series	20160331	—

X431PRO Actual Measurement: 2015 Porsche Cayenne A221 Service Lamp Resetting Method

Vehicle coverage: Porsche Cayenne A221, 2015, VIN=WP1AG2926FLA*****, as shown in Figure 1 and Figure 2.



Figure 1



Figure 2

Test user: Mr. Zhu, 13906542633, Battery shop at the east to bridge 4 at Luqiao district, Taizhou city, Zhejiang Province

Procedure:

1. Turn on the ignition switch.
2. Choose Service Lamp Reset V10.42.
3. Choose PORSCHE(Porsche). See Figure 3.




Figure 3

- 4. Choose Software Reset. See Figure 4.



Figure 4

- 5. Choose Automatic Scanning. See Figure 5.



Figure 5

- 6. Choose Cayenne. See Figure 6.




Figure 6

- 7. Choose Oil Reset. See Figure 7.




Figure 7

- 8. Enter the current date. See Figure 8.




Figure 8

- 9. Enter the current service date as required, such as 20160331. See Figure 9.



Figure 9

10. Click OK. The message "The service period has been successfully reset" is displayed. The vehicle service message disappears. See Figure 9.



Figure 9

11. Turn off the ignition switch and exit the software. Service lamp resetting is complete.