

Product Model	Date	Number
X-431 Pro series	Nov. 5 th , 2015	—

X-431 PRO Test: Mercedes-Benz Maybach Service Light Reset Instructions



Tested Model: Mercedes-Benz Maybach, VIN=WDBVF78J04A0*****, VIN=WDB2400771A0*****

NOTES:


1. Switch on the ignition before implementation. Do not start the engine.
2. Switch off the ignition after implementation. Wait for 10s. Then switch it on.

Operation Procedure:


1. Switch ignition ON. Do not start the engine.



2. Select the service light reset software version V10.30 or above.
3. Select "Mercedes-Benz" Menu.




4. Select "Passenger Car".




5. Select "Software Reset".




- 6. Select "Auto Scan" or "Manual Selection".



- 7. Select "Maybach".




- 8. It prompts to switch on the ignition. After this, it prompts "Communicating, please wait..." In about 1s, it displays "Confirm total service".



- 9. Select "Confirm total service", it shows oil type (level).



10. Select any type (level), it will display "Oil reset completed". Click OK to complete.



LAUNCH is dedicated to pursuing good functions and addressing customer needs. Follow LAUNCH, you will "make a little progress every day"!

