


【 X431PRO Measured articles】 2011 Maserati M145 maintenance lamp zero operation method

2016-03-29

Measured models: MaseratiM145, year2011, VIN=ZAMKK39E2B00*****




Cautions:

1. Park the vehicle on level ground. The installed sensor is very sensitive to the tilt of the vehicle, otherwise an incorrect measurement error will be displayed because the vehicle is not level.
2. The gear selector must be in P position.
3. After running the engine, wait for 10 minutes, because the vehicle running indicators to achieve a steady state. Used after each time

The sensor signal will give the correct output.

Operation instruction;

1. Turn ignition switch ON;
2. Choose "Europe";
3. Select "Maserati" V10.03 version;
4. Select "GRANTURISMO" models;
5. Select "M145";
6. Choose "gasoline";
7. Select "System Scan";
8. Select "IPC-dashboard combination", prompting ECU ID information, as shown in Figure 1;



确定

电子驻车制动器

Delphi气候控制

驻车传感器系统



首页



打印



帮助

golo官微

picture1

9. Select "special features", as shown in Figure 2;



版本信息

读故障码

清故障码

读数据流

读数据流

特殊功能



picture2

10. Select "maintenance information reset", as shown in Figure 3;



里程表设置

保养信息复位



picture3

11. Pay attention to reset service prompt information to ensure that the correct combination of the date on the instrument set, shown in Figure 4;

玛莎拉蒂 V10.03 > GRANTURISMO > M145 > 汽油 > 系统..

里程表设置

保养信息复位

保养信息复位

为了成功执行复位，请确保正确设置仪表组合上的日期！

确定

取消



首页



打印



golo 官微
帮助

picture4

12. After determining, the prompt program has been completed, as shown in Figure 5, the operation ended.





首页



打印



picture5