


【 X431 Remote Diagnose 】 2006Buick LuZun maintenance lamp return to zero operation method.




Note:

- 1.Switch on the ignition;
- 2.Keep the voltage more than 12V;
- 3.Perform on the good wifi internet. Otherwise, it will be caused diagnose abnormal.


Operation Procedure:

- 1.Select China GM V48.90 above ;
2. Select manual selection. Note: Do not choose online-programming. see pic2;




pic2

3. Select "Buick" see pic3;




pic3

4. Select 2006 "LuZun, see pic4;




pic4

5. Select “Engine control module” see pic5;



pic5

6. Select the third item ((C)3.0LV6 LZC”, see pic 6;



pic6

7. Select special function, see pic7;



pic7

8. Select engine oil reset, The current value of the engine oil life is 51 percent of the current value of the engine oil life before the reset operation, see pic8;




pic8

9. Click "Input", After input 100, reset see pic9;



10. Engine oil life value changed from 51% to 100%. It shows reset successfully. see pic10.



pic10

11. Switch off the key. Exit to the software.

Operation is finished.



长按指纹“识别二维码”关注 [golo官微](#)