

【 X431 Actual Measurement 】 Benz 251、 164、 X164 Chassis Power window activation operation method.

Function Description

This action test is mainly applicable to activate power window, applicable chassis : 251、 164、 X164。


Note:

Before testing, please follow these instructions as follow:

1. When executing the function, Do not use the outside force to control the car window roll up and down. The moving parts may cause a task, crushed, serious when even will cause the arms and legs cut off.
2. Please make sure there is no things placed nearby the door, when executing the function.
3. Please pay attention to the vehicles at any time when activating. Must keep enough safety distance with the vehicle.

Operation instructions

1. Choose Benz V48.00 above;
2. Choose manual selection;
3. Choose 251-R;
4. Choose long chassis;
5. Choose gasoline engine;
6. Choose left rudder driving;
7. Choose “251.156 - R350 L”, see as pic1;



pic1

8. Choose “Control Unit” see as pic2;



Pic2

9. Choose “Seat and car door” see as pic3



pic3

10. Choose “DCM_FR-door control unit” then it will prompt switch on the ignition, switch on the ignition then prompt “communicating, Please wait”, need to waiting for several seconds to enter into system, see as pic 4;



pic4

11. Choose “read fault code”, see as pic 5



Pic5

12. Read the fault code: 901 a, meaning is: the switch bus: at least one electric Windows CARDS in the state of the switch (contact adhesion) no side delete and ignore the fault codes. The component is not installed on the cars or vehicles. As shown in figure 6;

菜单				故障码显示				登录			
奔驰 V48.00 > 手动选择 > 251_R级 > 长底盘 > 汽油发动机 > 左舵驾驶 > 251.156 · R 350 L > 控制单元 > 座椅和车门 > DCM_FR - 右前门控制模块											
故障码	描述	状态	配件								
901A	开关总线:至少其中一个电动车窗开关卡在切换的状态(触点粘连).否则删除并忽略故障码:该元件未安装在该车系和(或)车型上.	存储	🔍								



Pic6


13. Return to the previous menu, choose “action test” ;

14. Choose “activate right-front power car window, see as pic7;



Pic7

15. Please read the related message and meet the conditions, in order to avoid bring you loss, as shown in figure 8.



Pic8



长按指纹“识别二维码”关注 **golo官微**