

# 【X431 Actual Measurement】 2007 Lacrosse Throttle Manual Programming operation Method.

Actual Measurement: 2007, VIN=LSGWS52X47S0\*\*\*\*, see pic1



Operation procedure:

- 1.Select China GM V48.40 above;
- 2.Select Lacrosse LuZun throttle programming .see pic1;



图2



图3

- 3.Select “Lacrosse LuZun” throttle manual programming”. Note: if select auto programming, It can read VIN and every module information. Ensure record all information. The main thing is to prevent programming failures in the middle of the stream and to use it when you can manually program your data and the recover data. Please make sure the power supply is adequate., see pic4;




图4

4. The VIN information is consistent with the actual car VIN, select “YES” see pic5;



图5

5. Note: Calibration is finished. If you want to program ,press “Yes” .Other step: Please follow the software interface to operate.
6. Note:
- a) When programming, If prompts error code 07: Software number is not exist , It means that this car doesn't support programming. Please feedback the VIN and version information to the launch company then exit to app.
  - b) When programming process goes wrong, Please do not start the engine ,it can use

manual programming to input this vehicle information and recover original data. Info including VIN, operation system, system, speed table, engine diagnose etc. These info can be read through auto-programming .

c) It will take 5-50mins to do programming .Please make sure power supply is adequate.

7. Other Items, please follow the interface prompts to operate.

7. 该车编程完成之后，启动着车并行驶试车，一切正常，问题解决。



长按指纹“识别二维码”关注 [golo官微](#)